THERMADYNE



HAZARD RATINGS 2-MODERATE INSIGNIFICANT



MATERIAL SAFETY DATA SHEET (MSDS)

DS) Hild Stell Wire

SECTION 1 - PRODUCT IDENTIFICATION

Product Type:

Solid Wire for Gas Metal Arc Welding

Product Name: Specification:

Thermal Arc 70S-6

AWS A5.18 ER70\$-6

Manufacturer:

Thermal Arc

2200 Corporate Drive

Trov. OH 45373 1-800-255-5846 Fax: 1-800-332-0946

Date Prepared:

March 19, 1998

SECTION 2 - HAZARDOUS INGREDIENTS

IMPORTANT! This section covers the material from which these products are manufactured. The fumes and gases produced when welding with normal use of these products are covered in Section 5.

Components	CAS No.	PEL. mg/m3	TLV. mg/m ₃	Wt. %
Manganese ¹	7439-96-5	5 (fume)	0.2	<2
Silicon	7440-21-3	5 (respirable) 15 (dust)	10 (respirable)	0.5-2.0
Iron	1309-37-1	10 (oxide fume)	5 (oxide fume)	Balance
Copper	7440-50-8	0.1	0.2 (fume)	<0.5

^{&#}x27;Subject to reporting requirements of Section 313 of the Emergency Planning & Community Right-to-Know Act of 1986 (SARA) and 40 CFR Part 372.

SECTION 3 - PHYSICAL/CHEMICAL CHARACTERISTICS

Solid copper coated steel wire.

SECTION 4 - FIRE AND EXPLOSION HAZARD DATA

(Nonflammable) Welding arc and sparks can ignite combustibles and flammables. Refer to American National Standard Z49.1 for fire prevention during the use of welding and allied procedures.

NFPA NUMERICAL CODES:

Health Hazard

Fire Hazard

Reactivity Hazard 0

SECTION 5 - REACTIVE

Hazardous Decomposition Products

Welding fumes and gases cannot be classified simply. The composition and quantity of both are dependent upon the metal being welded, the process, procedure and electrodes used. Other conditions which also influence the composition and quantity of the fumes and gases to which workers may be exposed include: coatings on the metal being welded (such as paint, plating, fluxes, or galvanizing), the number of welders and the volume of work area, the quality and amount of ventilation, the position of the welder's head with respect to the fume plume, as well as the presence of contaminants in the atmosphere (such as chlorinated hydrocarbon vapors from cleaning and degreasing activities).

When the electrode is consumed, the fume and gas decomposition products generated may be different in percent and form to the ingredients listed in Section 2. Fume and gas decomposition products, and not the ingredients in the electrode, are important. The concentration of a given fume or gas component may decrease or increase by many times the original concentration in the electrode. Also, new compounds not in the elec-

trodes may form. Decomposition products of normal operation include those originating from the volatilization, reaction, or oxidation of the materials shown in Section 2, plus those from the base metal and coating, etc., as noted above.

Reasonably expected decomposition products from normal use of these products include a complex of the oxides of the materials listed in Section 2, as well as carbon monoxide, carbon dioxide, ozone and nitrogen oxides. The fume limit for manganese may be reached before the general limit for welding fumes (5 mg/m²) is reached.

One recommended way to determine the composition and quantity of fumes and gases to which workers are exposed is to take an air sample inside the welder's helimet if worn or in the worker's breathing zone.

See applicable OSHA guidelines and ANSI/AWS F1.1 "Method for Sampling Airborne Particles Generated by Welding and Allied Processes" and "Characterization of Arc Welding Fume" available from the American Welding Society, 550 N.W. LeJeune Road, Miami, FL 33126.

SECTION 6 - HEALTH HAZARD DATA

Electric arc welding or oxy fuel welding may create one or more of the following health hazards:

ARC RAYS can injure eyes and burn skin.

HEAT RAYS (infrared radiation) from flame or hot metal can injure eyes.

ELECTRICAL SHOCK can KILL.

NOISE can damage hearing.

CARCINOGENICITY Chromium, nickel, cobalt, and their compounds are on the IARC and NTP lists as posing a carcinogenic risk to humans.

EMERGENCY AND FIRST AID PROCEDURES - Call for medical aid. Employ first aid techniques recommended by the American Red Cross.

SHIELDING GASES such as argon, helium and carbon dioxide are asphyxiants and adequate ventilation must be provided.

FUMES AND GASES can be dangerous to your health. COM-MON ENTRY IS BY INHALATION. Fumes may aggravate preexisting conditions. SHORT TERM (ACUTE) - overexposure to welding furnes may result in discomfort such as dizziness, nausea, or dryness or irritation of nose, throat, or eyes.

Manganese furne may cause flu like symptoms (metal furne fever).

LONG TERM (CHRONIC) - overexposure to welding fumes can lead to siderosis (iron deposits in the lung) and affect pulmonary function.

Long term overexposure to manganese compounds may affect the central nervous system. Symptoms include muscular weakness and tremors similar to Parkinson's disease. Behavioral changes and changes in handwriting may also appear.

THRESHOLD LIMIT VALUE - The ACGIH 1994-95 recommended limit for welding fumes not otherwise classified (NOC) is 5mg/m³. TLV - TWA's may be used and OSHA PELS's must be used as a guide in the control of health hazards. See Section 5 for specific fume constituents which may modify the types of air-born contaminates.

SECTION 7 - PRECAUTIONS FOR SAFE HANDLING & USE/APPLICABLE CONTROL MEASURES

Read and understand the manufacturer's instructions and the precautionary label on the product. See American National Standard Z49.1, Safety in Welding, Cutting, and Allied Processes, published by the American Welding society, 550 N.W. LeJeune Road, Miami, FL 33126 and OSHA Publication 2206 (29CFR1910), US Government Printing Office, Washington, D.C. 20402 for more detail on many of the following.

VENTILATION - Use enough ventilation, local exhaust at the arc, or both, to keep the fumes and gases below TLV's in the worker's breathing zone and the general area. Train the welder to keep his head out of the fumes.

RESPIRATORY PROTECTION - Use respirable fume respirator or air supplied respirator when welding in confined space or where local exhaust or ventilation does not keep exposure below TLV.

EYE PROTECTION - Wear helmet or use face shield with filter lens. As a rule of thumb, start with a shade that is too dark to see the weld zone then go to the next lighter shade which gives sufficient view of the weld zone. Provide protective screens and flash goggles, if necessary to shield others.

PROTECTIVE CLOTHING - Wear head, hand and body protection which help to prevent injury from radiation, sparks, and electrical shock. See ANSI Z49.1 at a minimum this includes welder's gloves and a protective face shield, and may include arm protectors, aprons, hats shoulder protection, as well as dark substantial clothing. Train the welder not to touch live electrical parts and to insulate himself from work and ground.

PROCEDURE FOR CLEANUP OF SPILLS OR LEAKS - Not applicable.

WASTE DISPOSAL METHOD - Prevent waste from contaminating surrounding environment. Discard any product, residue, disposable container or liner in an environmentally acceptable manner, in full compliance with federal, state and local regulations.

The information herein is supplied in good faith, but no warranties are expressed or implied.

For further information contact:

Thermal Arc 2200 Corporate Drive Troy, OH 45373 1-800-255-5846

SECTION 8 - DEFINITIONS

PEL

TLV

CAS No. Chemical Abstracts Service Number TWA Time Weighted Average
OSHA U.S. Department of Labor, Occupational Safety and STEL Short Term Exposure Limit

Health Administration CLG Ceiling Limit
Permissible Exposure Level NOC Not Otherwise Classified

ACGIH American Conference of Governmental Industrial IARC International Agency for Research on Cancer

Hygienists NTP National Toxicology Program
Threshold Limit Value

The opinions expressed in this MSDS are those of qualified experts of Thermadyne Industries, Inc. We believe that the information contained herein is current as of the date of this MSDS. Since the use of this information and these opinions and the conditions of use of these products are not within the control of the Thermadyne Industries, Inc., it is the user's obligation to determine the conditions of sale use of these products.

Form No. 84-9822 (5/98) © Thermal Arc Inc., 1998 www.thermalarc.com Printed in U.S.A.