Revised March 25, 1987

LENOX Band-Ade™ Sawing Fluid MATERIAL SAFETY DATA SHEET

	SECTION I		
MANUFACTURER'S NAME American Saw & Mfg. Company	(S.I.C.)	EMERGENCY TELEPHONE NO. (413) 525-3961	
ADDRESS (Number, Street, City, State and ZIP Code) 301 Chestnut St., East Longmeadow,	MA 01028		
CHEMICAL NAME AND SYNONYMS A sawing fluid		TRADE NAME AND SYNONYMS LENOX BAND-ADE™	
CHEMICAL FAMILY N/A	FORM	Proprietary	

PAINTS, PRESERVATIVES & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS	0		BASE METAL	0	
CATALYST	0		ALLOYS	0	
VEHICLE	0		METALLIC COATINGS	0	
SOLVENTS	0		FILLER METAL PLUS COATING OR CORE FLUX	0	
ADDITIVES	0		OTHERS	0	
OTHERS	0				
HAZARDOUS MIXTURE	ES OF O	THER LIQ	UIDS, SOLIDS, OR GASES	%	TLV (Units)
This product does not contain any ingredi	ient set	forth by th	ne Occupational Safety and		
Health Administration or by the Environme	ental Pr	otection A	gency on their list of hazardous chemicals.		

SECTION III - PHYSICAL DATA					
BOILING POINT (°F.)	218°F	SPECIFIC GRAVITY (H ₂ O=1)	1.29		
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT, VOLATILE BY VOLUME (%)	N/A		
VAPOR DENSITY (AIR=1)	N/A	EVAPORATION RATE	N/A		
SOLUBILITY IN WATER	Complete				

SECTION IV - FIRE AND EXPLOSION HAZARD DATA								
FLASH POINT (Method used) None (COC)	FLAMMABLE LIMITS	Lel	Uel					
EXTINGUISHING MEDIA N/A This material is not combusti	ible.	,						
SPECIAL FIRE FIGHTING PROCEDURES No special procedu	ires needed.	4						
UNUSUAL FIRE AND EXPLOSION HAZARDS								
None								

	SECTION V - HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE	None established
EFFECTS OF OVEREXPOSURE	None
EMERGENCY AND FIRST AID PR	OCEDURES
Wash eyes with v	water. Wash skin with soap and water. Soaked clothing should be changed for comfort.
See a physician s	should individual so desire as a precautionary measure.

		SE	CTION VI - F	REACTIVITY DATA	
STABILITY	LITY UNSTABLE		CONDITIONS	TO AVOID	
	STABLE	X			
	(Materials to avoid)	Stro	ng acids and	strong bases	
HAZARDOUS DECC	MPOSITION PRODUCTS				
HAZARDOUS	MAY OCCUP	3		CONDITIONS TO AVOID	0391 141
POLYMERIZATION	WILL NOT O	CCUR	X		

SECTION VII - SPILL OR LEAK PROCEDURES	
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	
Small amounts, flush with water. Large amounts should be absorbed with suitable material.	
and disposed of in accordance with local, state and federal regulations.	
WASTE DISPOSAL METHOD	
Material is biodegradable.	
	+

	SECTION	VIII - SPECIAL PI	ROTECTION INF	ORMATION	
RESPIRATORY PROTEC	TION (Specify type)	None needed	2		
VENTILATION	LOCAL EXHAUST	Not needed		SPECIAL	
	MECHANICAL (General)	Normal ventilation		OTHER	
PROTECTIVE GLOVES	Not needed (See Section IX)		EYE PROTECTION	Approved safety glasses as required by employer.	
OTHER PROTECTIVE EC	in a second seco			and the state of t	-

SECTION IX - SPECIAL PRECAUTIONS			
PRECAUTIONS TO BE T	AKEN IN HANDLING AND STORING		
Avoid freezing			
OTHER PRECAUTIONS	Those sensitive to skin irritation may wish to consult their safety director or physician for		
	appropriate protective measures.		