# Safety Data Sheet



1. Identification			
Product Name:	Flowpatch	Revision Date:	11/8/2016
Product Identifier:	A050606	Supercedes Date:	11/30/2015
Product Use/Class:	Concrete Patch/WATCO Floors		
Supplier:	Watco Industrial Flooring 11 Hawthorn Parkway Vernon Hills, IL 60061 USA	Manufacturer:	Watco Industrial Flooring 11 Hawthorn Parkway Vernon Hills, IL 60061 USA
Preparer:	Regulatory Department		
Emergency Telephone:	24 Hour Hotline: 847-367-7700		

# 2. Hazard Identification

### Classification

Symbol(s) of Product



Signal Word Danger

### Possible Hazards

4% of the mixture consists of ingredient(s) of unknown acute toxicity.

#### **GHS HAZARD STATEMENTS**

May cause an allergic skin reaction.
Causes serious eye damage.

P280Wear protective gloves/protective clothing/eye protection/face protection.P305+P351+P338IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.P310If exposed immediately call a POISON CENTER or doctor/physician.P261Avoid breathing dust/fume/gas/mist/vapours/spray.P272Contaminated work clothing should not be allowed out of the workplace.P302+P352IF ON SKIN: Wash with plenty of soap and water.P333+P313If skin irritation or rash occurs: Get medical advice/attention.P321For specific treatment see labelP501Dispose of contents/container in accordance with local, regional and national regulations.GHS SDS PRECAUTIONARY STATEMENTSWash contaminated clothing before reuse.	GISLADEL FREGAUTIONANT STATE	
P310If exposed immediately call a POISON CENTER or doctor/physician.P261Avoid breathing dust/fume/gas/mist/vapours/spray.P272Contaminated work clothing should not be allowed out of the workplace.P302+P352IF ON SKIN: Wash with plenty of soap and water.P333+P313If skin irritation or rash occurs: Get medical advice/attention.P321For specific treatment see labelP501Dispose of contents/container in accordance with local, regional and national regulations.GHS SDS PRECAUTIONARY STATEMENTS	P280	Wear protective gloves/protective clothing/eye protection/face protection.
P261Avoid breathing dust/fume/gas/mist/vapours/spray.P272Contaminated work clothing should not be allowed out of the workplace.P302+P352IF ON SKIN: Wash with plenty of soap and water.P333+P313If skin irritation or rash occurs: Get medical advice/attention.P321For specific treatment see labelP501Dispose of contents/container in accordance with local, regional and national regulations.GHS SDS PRECAUTIONARY STATEMENTS	P305+P351+P338	
P272Contaminated work clothing should not be allowed out of the workplace.P302+P352IF ON SKIN: Wash with plenty of soap and water.P333+P313If skin irritation or rash occurs: Get medical advice/attention.P321For specific treatment see labelP501Dispose of contents/container in accordance with local, regional and national regulations.GHS SDS PRECAUTIONARY STATEMENTS	P310	If exposed immediately call a POISON CENTER or doctor/physician.
P302+P352IF ON SKIN: Wash with plenty of soap and water.P333+P313If skin irritation or rash occurs: Get medical advice/attention.P321For specific treatment see labelP501Dispose of contents/container in accordance with local, regional and national regulations.GHS SDS PRECAUTIONARY STATEMENTS	P261	Avoid breathing dust/fume/gas/mist/vapours/spray.
P333+P313If skin irritation or rash occurs: Get medical advice/attention.P321For specific treatment see labelP501Dispose of contents/container in accordance with local, regional and national regulations.GHS SDS PRECAUTIONARY STATEMENTS	P272	Contaminated work clothing should not be allowed out of the workplace.
P321 For specific treatment see label   P501 Dispose of contents/container in accordance with local, regional and national regulations.   GHS SDS PRECAUTIONARY STATEMENTS	P302+P352	IF ON SKIN: Wash with plenty of soap and water.
P501 Dispose of contents/container in accordance with local, regional and national regulations. GHS SDS PRECAUTIONARY STATEMENTS	P333+P313	If skin irritation or rash occurs: Get medical advice/attention.
GHS SDS PRECAUTIONARY STATEMENTS	P321	For specific treatment see label
	P501	Dispose of contents/container in accordance with local, regional and national regulations.

# 3. Composition/Information On Ingredients

#### HAZARDOUS SUBSTANCES

Chemical Name	CAS-No.	<u>Wt.%</u> Range	GHS Symbols	GHS Statements
Crystalline Silica / Quartz	14808-60-7	50-75	Not Available	Not Available
Portland Cement	65997-15-1	2.5-10	GHS05-GHS07	H315-317-318-335
Titanium Dioxide	13463-67-7	1.0-2.5	Not Available	Not Available

## 4. First-aid Measures

**FIRST AID - EYE CONTACT:** Immediately flush eyes with plenty of water for at least 15 minutes holding eyelids open. Get medical attention. Do NOT allow rubbing of eyes or keeping eyes closed.

FIRST AID - SKIN CONTACT: Wash skin with soap and water. Remove contaminated clothing. Get medical attention if irritation develops or persists.

**FIRST AID - INHALATION:** Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Get immediate medical attention. Do NOT use mouth-to-mouth resuscitation. If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical assistance immediately.

FIRST AID - INGESTION: If swallowed, rinse mouth with water. If feeling unwell, get medical attention.

## 5. Fire-fighting Measures

**EXTINGUISHING MEDIA:** Alcohol Film Forming Foam, Carbon Dioxide, Dry Chemical, Dry Sand, Water Fog

**UNUSUAL FIRE AND EXPLOSION HAZARDS:** No unusual fire or explosion hazards noted. Keep containers tightly closed. FLASH POINT IS TESTED TO BE GREATER THAN 200 DEGREES F.

SPECIAL FIREFIGHTING PROCEDURES: Water may be used to cool closed containers to prevent buildup of steam.

### 6. Accidental Release Measures

**STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED:** Dispose of according to local, state (provincial) and federal regulations. Do not incinerate closed containers. Sweep up gently to avoid dust cloud formation.

## 7. Handling and Storage

**HANDLING:** Wash thoroughly after handling. Wash hands before eating. Remove contaminated clothing and launder before reuse. Use only with adequate ventilation. Follow all MSDS/label precautions even after container is emptied because it may retain product residues. Avoid breathing fumes, vapors, or mist. Avoid contact with eyes, skin and clothing. **STORAGE:** Store in a dry, well ventilated place. Keep container tightly closed when not in use.

## 8. Exposure Controls/Personal Protection

Chemical Name	CAS-No.	Weight % Less Than	ACGIH TLV- TWA	ACGIH TLV- STEL	OSHA PEL-TWA	OSHA PEL- CEILING
Crystalline Silica / Quartz	14808-60-7	55.0	0.025 mg/m3	N.E.	50 µg/m3	N.E.
Portland Cement	65997-15-1	5.0	1 mg/m3	N.E.	15 mg/m3	N.E.
Titanium Dioxide	13463-67-7	5.0	10 mg/m3	N.E.	15 mg/m3	N.E.

#### PERSONAL PROTECTION

**ENGINEERING CONTROLS:** Use process enclosures, local exhaust ventilation, or other engineering controls to control airborne levels below recommended exposure limits. Prevent build-up of vapors by opening all doors and windows to achieve cross-ventilation.

**RESPIRATORY PROTECTION:** A respiratory protection program that meets OSHA 1910.134 and ANSI Z88.2 requirements must be followed whenever workplace conditions warrant a respirator's use.

SKIN PROTECTION: Use gloves to prevent prolonged skin contact. Nitrile or Neoprene gloves may afford adequate skin protection.

EYE PROTECTION: Use safety eyewear designed to protect against splash of liquids.

**OTHER PROTECTIVE EQUIPMENT:** Refer to safety supervisor or industrial hygienist for further guidance regarding types of personal protective equipment and their applications.

**HYGIENIC PRACTICES:** Wash thoroughly with soap and water before eating, drinking or smoking. Remove contaminated clothing immediately and launder before reuse.

9. Physical and Chemical Properties					
Appearance:	Particulate Solid	Physical State:	Solid		
Odor:	None	Odor Threshold:	N.E.		
Relative Density:	2.900	pH:	N.A.		
Freeze Point, °C:	N.D.	Viscosity:	N.D.		
Solubility in Water:	None	Partition Coefficient, n-octanol/			
Decompostion Temp., °C:	N.D.	water:	N.D.		
Boiling Range, °C:	-18 - 3,000	Explosive Limits, vol%:	N.A N.A.		
Flammability:	Does not Support Combustion	Flash Point, °C:	94		
Evaporation Rate:	Slower than Ether	Auto-ignition Temp., °C:	N.D.		
Vapor Density:	N.A.	Vapor Pressure:	N.D.		

(See "Other information" Section for abbreviation legend)

## 10. Stability and Reactivity

CONDITIONS TO AVOID: Avoid contact with strong acid and strong bases.

INCOMPATIBILITY: Avoid contact with water. Incompatible with strong oxidizing agents, strong acids and strong alkalies.

HAZARDOUS DECOMPOSITION: When heated to decomposition, it emits acrid smoke and irritating fumes.

HAZARDOUS POLYMERIZATION: Will not occur under normal conditions.

**STABILITY:** This product is stable under normal storage conditions.

## 11. Toxicological information

EFFECTS OF OVEREXPOSURE - EYE CONTACT: May cause eye irritation. Irritating, and may injure eye tissue if not removed promptly.

**EFFECTS OF OVEREXPOSURE - SKIN CONTACT:** May cause severe irritation. May cause dryness, cracking, irritation, and chemical burns. May produce cement dermatitis due to primary irritation from alkaline, hygroscopic, and abrasive properties. Low hazard for usual industrial handling or commercial handling by trained personnel.

**EFFECTS OF OVEREXPOSURE - INHALATION:** Avoid breathing fumes, spray, vapors, or mist. High gas, vapor, mist or dust concentrations may be harmful if inhaled.

EFFECTS OF OVEREXPOSURE - INGESTION: Expected to be a low ingestion hazard.

**EFFECTS OF OVEREXPOSURE - CHRONIC HAZARDS:** Contains Titanium Dioxide. Titanium Dioxide is listed as a Group 2B-"Possibly carcinogenic to humans" by IARC. No significant exposure to Titanium Dioxide is thought to occur during the use of products in which Titanium Dioxide is bound to other materials, such as in paints during brush application or drying. Risk of overexposure depends on duration and level of exposure to dust from repeated sanding of surfaces or spray mist and the actual concentration of Titanium Dioxide in the formula. (Ref: IARC Monograph, Vol. 93, 2010)

PRIMARY ROUTE(S) OF ENTRY: Eye Contact, Ingestion, Inhalation, Skin Absorption, Skin Contact

#### ACUTE TOXICITY VALUES

#### The acute effects of this product have not been tested. Data on individual components are tabulated below:

CAS-No.	<u>Chemical Name</u>	Oral LD50	Dermal LD50	Vapor LC50
14808-60-7 13463-67-7	Crystalline Silica / Quartz Titanium Dioxide	5500 mg/kg Rat >10000 mg/kg Rat	5500 2500 mg/kg	100 mg/L N.I.
10400-07-7			2000 mg/kg	IN.I.

N.I. - No Information

## 12. Ecological Information

ECOLOGICAL INFORMATION: Product is a mixture of listed components.

## 13. Disposal Information

**DISPOSAL INFORMATION:** Dispose of material in accordance to local, state, and federal regulations and ordinances. Do not allow to enter waterways, wastewater, soil, storm drains or sewer systems.

## 14. Transport Information

	Domestic (USDOT)	International (IMDG)	<u>Air (IATA)</u>	<u>TDG (Canada)</u>
UN Number:	N.A.	N.A.	N.A.	N.A.
Proper Shipping Name:	Not Regulated	Not Regulated	Not Regulated	Not Regulated
Hazard Class:	N.A.	N.A.	N.A.	N.A.
Packing Group:	N.A.	N.A.	N.A.	N.A.
Limited Quantity:	No	No	No	No

## 15. Regulatory Information

## U.S. Federal Regulations:

### **CERCLA - SARA Hazard Category**

This product has been reviewed according to the EPA 'Hazard Categories' promulgated under Sections 311 and 312 of the Superfund Amendment and Reauthorization Act of 1986 (SARA Title III) and is considered, under applicable definitions, to meet the following categories:

Acute Health Hazard, Chronic Health Hazard

#### Sara Section 313:

This product contains the following substances subject to the reporting requirements of Section 313 of Title III of the Superfund Amendment and Reauthorization Act of 1986 and 40 CFR part 372:

No Sara 313 components exist in this product.

#### **Toxic Substances Control Act:**

This product contains the following chemical substances subject to the reporting requirements of TSCA 12(b) if exported from the United States:

No TSCA 12(b) components exist in this product.

# 16. Other Information

HMIS RAT Health:	TINGS 1*	Flammability:	0	Physical Hazard:	0	Personal Protection:	х
NFPA RA	TINGS						
Health:	1	Flammability:	0	Instability	0		
VOLATILE	ORGA	NIC COMPOUN	DS, g/L:	0			
SDS REVI	SION D	ATE:	11/8/2016				
REASON F	FOR RE	VISION:	Substance H Substance H Substance a 02 - Hazard 03 - Compo 08 - Expose 11 - Toxico	Regulatory CAS Number C Hazardous Flag Changed Hazard Threshold % Chang and/or Product Properties C I Identification Isition/Information on Ingre ure Controls/Personal Prote logical Information tory Information ) Changed	ged Changed dients	in Section(s):	

Legend: N.A. - Not Applicable, N.E. - Not Established, N.D. - Not Determined

The manufacturer believes, to the best of its knowledge, information and belief, the information contained herein to be accurate and reliable as of the date of this safety data sheet. However, because the conditions of handling, use, and storage of these materials are beyond our control, we assume no responsibility or liability for personal injury or property damage incurred by the use of these materials. The manufacturer makes no warranty, expressed or implied, regarding the accuracy or reliability of the data or results obtained from their use. All materials may present unknown hazards and should be used with caution. The information and recommendations in this material safety data sheet are offered for the users' consideration and examination. It is the responsibility of the user to determine the final suitability of this information and to comply with all applicable international, federal, state, and local laws and regulations.